1

Actual status: 14th May 2019

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
1.	BE-01/77 SZD-42-1 "JANTAR-2"	Gliders of following fact. numbers: X-126, B-776 to B-781.	Extension of the flight limitations.		
2.	BE-02/78 SZD-42-2 "JANTAR-2B"	Gliders of following fact. numbers: X-131, B-858 to B-866 and B-868 to B-870.	Extension of the flight limitations.		
3.	BE-03/79 SZD-42-2 "JANTAR-2B"	Gliders of following fact. numbers: X-131, B-858 to B-866 and B-868 to B-870.	Replacement of page in Technical Service Manual.		
4.	BE-04/79 SZD-42-2 "JANTAR-2B"	Gliders of following fact. numbers: X-131, B-856 to B-866 and B-868 to B-870.	Change in Flight Manual.		
5.	-	-	-	-	Item used as BE- 05/78 "Jantar Std"
6.	-	-	-	-	Item used as BE- 06/79 "Jantar Std"
7.	BE-07/80 "JANTAR"	All below mentioned gliders: SZD-37x, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, SZD-42, SZD-42-1, SZD-42-2, SZD-48 and SZD-48-1.	Lacquer removal from the spar root end, rood end and root rib, then painting with colourless lacquer.	Introduce during nearest pause in flying.	
8.	BE-08/79 "JANTAR"	All gliders: SZD-37x, SZD-38, SZD-38A, SZD-42, SZD-42-1, SZD-42-2.	Change of overhaul life time up to 1500 flying hours and inspections relevant to this.	After completing previous established flying hours of after 6 years of operation.	
9.	BE-09/80 "JANTAR-2B"	Gliders "JANTAR-2B" of fact. numbers mentioned below: X-131, B-658 to B- 875, B-908 and B-1065.	Securing of the auxiliary spring for front undercarriage arm retracting against the automatic disconnection of the fuselage frame work hook.	Introduce <u>at once.</u>	
10.	-	-	-	-	Item used as BE- 10/80 "Jantar"
11.	-	-	-	-	Item used as BA- 011/81 "Jantar"
12.	BK-012/81 "JANTAR-2"	Glider types: SZD-42, 42-1 and 42-2 up to B-1074 incl.	Protection of the polyamide bearing sleeve of the lower rudder mounting against the possibility of its cut-off resulted by groundroughness shocks.	Introduce at once.	
13.	-	-	-	-	Item used as BS- 13/81 "Jantar"

ZAKŁAD SZYBOWCOWY "JEŻÓW" 58-521 Jeżów Sudecki ul. Długa 93

Tel./Fax (33) 829 33 27

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
14.	-	-	-	-	Item used as BK- 014/81 "Jantar"
15.	BK-015/81 "JANTAR"	Glider types mentioned below: SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, 41A, 41B, <u>SZD-42, 42-1, SZD-42-2</u> up to serial No. B-1126 incl., SZD-48, SZD-48-1 up to serial No. B-1195 incl. and SZD-49.	Securing of the instrument panel cover against the unintentional shifting out of the fixing.	Introduce after receive Bulletin.	
16.	BR-016/81 "JANTAR"	Below listed glider types: SZD-37, SZD-38, SZD-38A, SZD-42, SZD-42-1 Fact. Nos X-128, from B-776 to B-792, B-867, B-876, SZD-42-2 Fact. Nos X-131, from B-858 to B-866, from B-868 to B-879, B-908, from B-934 to B-953, B-964, from B-1065 to B-1074, from B-1125 to B-1134 and from B-1305 to B-1214; SZD-48 and SZD-48-1.	Replacement of the bolts connecting the aileron control lever in wing with aileron.	The change described in the Bulletin shall be introduced up to 30 Sept. 1983.	
17.	BI-017/82 "JANTAR"	Below listed glider types: SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, SZD-42, SZD-42-1, SZD-42-2, SZD-48 and SZD-48-1.	The list of issued Bulletins for Jantar gliders updated condition on day April 30, 1982	To be dealt as the information.	
18.	BA-018/83 "JANTAR-2B"	Below listed glider types: <u>SZD-42-2</u> Fact. Nos B-1066, from B-1068 to B-1074, from B-1125 to B-1134 and from B-1305 to B-1312.	Inspection of glue joints between the inner wing spar to skin connection in the vicinity of inner to outer wing panels fitting.	The recommendations contained in this Bulletin shall be introduced immediately.	
19.	BK-019/83 "JANTAR"	Below listed glider types: SZD-37x, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, SZD-42, SZD-42-1, SZD-42-2, SZD-48 and SZD-48-1.	Replacement of compensation volume fastening clamps in the instrument panel.	Bulletin recommended by the producer. The way of introducing is left for the user's decision.	

ZAKŁAD SZYBOWCOWY "JEŻÓW" 58-521 Jeżów Sudecki ul. Długa 93

Tel./Fax (33) 829 33 27

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
20.	buttetin No	Ref. to Fact. Nos	Contents of butterin	way or incroducing	BE-020/83 "Jantar
20.	-	-	-	-	Std 3" concerns:
					SZD-48-3 only.
24	_			_	BE-021/84 "JANTAR
21.	-	-	-	-	
					Std 3" concerns
22					SZD-48-3 only.
22.	-	-	-	-	BE-022/85 "JANTAR
					Std 3" concerns
					SZD-48-3 only.
23.	-	-	-	-	BE-023/85 "JANTAR
					Std" concerns
					SZD-48, SZD-48-1
2.1		1 2 10 2			and SZD-48-3.
24.	BE-024/85	Concerns the SZD-42-2	Revisions in Technical Description, Technical Service	Obligatory when this	
	"JANTAR-2B"	"Jantar 2B" gliders with	Manual for SZD-42-2 "Jantar 2B" due to the installation	Bulletin is obtained.	
		factory installed hook or	of the towing hooks of SZD-III-A-56 type P on some		
		hooks of SZD-III P model, as	gliders of above model.		
		well as replaced in			
		operation on base of			
		Bulletin BS-03/78 SZD-38A			
		Jantar 1. The statements of			
		this bulletin have been			
		introduced into the glider			
		associated documents for			
25		ships from Fact. No B-1486.			DE COE (OF # LANEAR
25.	-	-	-	-	BE-025/85 "JANTAR
					Std 3" concerns
24					SZD-48-3 only.
26.	-	-	-	-	BE-026/86 "JANTAR
					Std" concerns:
					SZD-41, SZD-41A,
					SZD-48-1
2=	DE 007/0/	B. L.		T. D. II	and SZD-48-3.
27.	BE-027/86	Below listed glider types:	Extension of life-time for cables with metal core for	The Bulletin is	
	"JANTAR"	SZD-38A, SZD-41A, <u>SZD-42-</u>	rudder control system of Jantar gliders	obligatory from the	
		1, SZD-42-2, SZD-48, SZD-		date of issue	
		48-1 and SZD-48-3 (does not		(receipt).	
		concern SZD-37 (X-105)).			

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
28.	-	-	-	-	BE-028/87 "JANTAR 1" concerns SZD- 38A only.
29.	-	-	-	-	BE-029/87  "JANTAR" concerns SZD-37, SZD-38, SZD-41, SZD-41A, SZD-41B, SZD-48, SZD-48-1 and SZD-48-3.
30.	BE-030/87 "JANTAR-2B"	The gliders of <u>SZD-42-2</u> "JANTAR-2B" type of Fact. Nos X-121 and from B-858 to B-1672 incl.	Inspection of fitting the balancing weights in the fuselage nose.	Obligatory when this Bulletin is received.	
31.	BE-031/87 "JANTAR"	Below listed glider types: <u>SZD-42</u> "JANTAR-2" (X-119 and X-120), <u>SZD-42-1</u> "JANTAR-2A" (X-128 and from B-776 to B-867) and <u>SZD-42-2</u> "JANTAR-2B" (from B-858 higher Nos).	Revision of life-time of SZD-42 "Jantar2", SZD-42-1 "Jantar 2A" and SZD-42-2 "Jantar 2B" sailplanes from 1500 into 3000 flying hours.	Acc. to user's decision.	
32.	BR-032/87 "JANTAR"	Below listed glider types: SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-42, SZD-42-1, SZD-42-2, SZD-48, SZD-48-1, SZD-48-3 and SZD-48-3M.	Compensation of plays in wing-to-fuselage connection / or middle wing-to-wingtip/ of Jantar sailplanes family.	In case the "excessive" plays appear, as defined in the Bulletin, obligatory to be introduced.	
33.	-	-	-	-	BE-033/88 "JANTAR Std 2" concerns: SZD-48 and SZD-48-1.
34.	-	-	-	-	BE-034/88 "JANTAR Std" concerns: SZD-41, SZD-41-1 (SZD-41A), and SZD-41B.
35.	-	-	-	-	BE-035/88 "JANTAR Std 3" concerns SZD-48-3 only.

ZAKŁAD SZYBOWCOWY "JEŻÓW" 58-521 Jeżów Sudecki ul. Długa 93

Tel./Fax (33) 829 33 27

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
36.	-	-	-		BE-036/89
30.					"JANTAR-1"
					concerns
					SZD-38A only.
37.	_	_	_	_	BE-037/89 "JANTAR
37.					Std" concerns:
					1) SZD-41A
					(except of
					B-700 to B-
					703)
					2) SZD-48 and
					SZD-48-1
					(except of
					B-1266 and
					B-1268.
38.	BE-038/89	Glider types: <u>SZD-42-2</u>	Complementation of the undercarriage locking in the	Acc. to user's decision	
	"JANTAR-2B"	"JANTAR-2B" Fact. Nos	retracted position.	(as recommendation).	
		X-131 and from B-858 to			
		B-1563 (except of B-859).			
39.	BE-039/90	Glider types:	Inspection for correct assembling of aileron control	In case of	
	"JANTAR"	1) SZD-42-1 "JANTAR-	lever in the wing guides.	disassembling of inner	
		2A" (X-128 and from B-		aileron of its shifting-	
		776 to B-792, B-867 and		off out of the hinges	
		B-876);		the inspection is to be	
		2) SZD-42-2 "JANTAR-		carried on	
		2B" (X-131 and from B-		immediately.	
40	DE 040400	858 to B-1131).	Produce and of the design of the design of the	A (	
40.	BE-040/90	Below listed glider types:	Replacement of the driving pin of the claw-coupling	Acc. to user's	
	"JANTAR"	SZD-38A, SZD-41A, <u>SZD-42-</u>	body in the automatic control system connection of the	decision.	
		1, SZD-42-2, SZD-48, SZD-	Jantar family gliders.		
41.	BI-041/90	48-1 and SZD-48-3.	Actualization of "List of Bulletins issued up to date for	To be dealt as the	
41.	"JANTAR"	All types of "JANTAR" family gliders.	Jantar family gliders' (status on 31 May 1990)	information.	
42.	JANTAN	rannity gliders.	Januar raining griders (status OH 31 May 1990)	- יייייייייייייייייייייייייייייייייייי	BE-042/92
42.	_	_	-	_	"JANTAR Std 3"
					concerns SZD-48-3
					only.
					Officy.

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
43.	BE-043/92	Bulletin covers these	Appreciation of wear degree of the push-rode	As necessary.	Remarks
	"JANTAR"	sailplanes of "Jantar"	duraluminium tube surface in the location of contact	7.5	
		family where the ball	with the ball bearing being used as the guiding rollers in		
		bearings have been used as	the guides.		
		the rollers of the push-rod			
		guides, which contact the			
		push-rod (metal on metal).			
		It is used in the sailplanes			
		of SZD-48-1 "Jantar Std 2",			
		SZD-48-3 "Jantar Std 3" and			
		SZD-42-2 "Jantar-2B" type.			
44.	-	-	-	-	BE-044/93 "JANTAR Std" concerns SZD-41, SZD-41A and SZD- 41B types.
45.	BE-045/93	All Jantar gliders:	Cancellation of every 6 years inspection for all types of	Obligatory when this	
	"JANTAR"	SZD-37x, SZD-38, SZD-38A, SZD-42, 42-1, 42-2, SZD-48, 48-1, 48-3	Jantar and Jantar Standard gliders.	Bulletin is received.	
		SZD-41, 41A, 41B, 41-1.			
46.	BE-046/95 "JANTAR"	All gliders of SZD-42, SZD-42-1 and SZD-42-2 with four panel wings.	Performing the detailed inspection of pin installation in outboard wing spar end.	Immediately after receiving the Bulletin.	
47.	-	-	-	-	NOT ISSUED
48.	BA-048/2002	SZD-42 Jantar 2 SZD-42-1 Jantar 2A SZD-42-2 Jantar 2B	Procedure of inspection of rudder control cable attachment at cockpit front floor.	Mandatory, immediately after receiving the Bulletin	
49.	BE-049/42/2018	SZD-42-2 Jantar 2B	Extension of glider service life beyond 3000 flying hours	Acc. to user's decision	
		Factory Nos: B-869, B-951, B-1130, B-1324	At operator discretion		
50.	BE-050/42/2019	SZD-42 Jantar 2 SZD-42-1 Jantar 2A	Extension of glider service life beyond 3000 flying hours	Acc. to user's decision	
		SZD-42-1 Jantar 2B			
		Except Nos: B-869, B-951,			
		B-1130, B-1324			