1

Actual status: 1st May 2008

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
1	Bulletin of changes	Serial No W-290 and	Replacing the pages in Technical Service and Flight	After receipt the	Only Polish and
	No 10/SZD-30 "PIRAT"	from W-314 to W-328	Manuals	pages for	German language
	B. II	from W-389 to W-399		replacement	version
2	Bulletin of changes	Serial No W-290 and	Additional washer in the elevator control system under	To be introduced	Only Polish
	No 11/SZD-30 "PIRAT"	from W-314 to W-328 from W-389 to W-399	the pin head	immediately	language version
3	Bulletin No BR-001/71	Serial No from B-403 to B-	Removal of the airbrake plate jamming during locking	To be introduced	Only Polish
	"PIRAT"	413	at airspeed V=200 to 250 km/h	immediately	language version
4	Bulletin No BR-001/72	ad.1 at user's decision	1. Ballast installation on frame No 1	ad. 1 at user's	
	"PIRAT"	ad.2 from W-314 to W-328 from W-389 to W-418	Inspection of stabilizer angle of wing setting	decision	
		from B-294 to B-473		ad. 2 to be introduced	
				immediately	
5	Bulletin No BR-002/72	The gliders	Securing:	To be introduced	
	"PIRAT"	from W-314 to W-328	Stops on the control column against the	immediately	
		from W-389 to W-418	disadjustment		
		from B-294 to B-473	The elevator push-rod fork end against		
6	Bulletin No 003/72	All gliders having mentioned	unscrewing /at removed push-rod/ Repair of the leading edge operated damages and	Acc. to user's decision	
0	"PIRAT"	damages	others gliders damages of external surfaces	Acc. to user's decision	
		_			
7	Bulletin No BE-004/72	All gliders operated by GST	Change of flight conditions of SZD-30 "PIRAT" gliders	Acc. to GST	
	"PIRAT"		for GST /East Germany/	requirements / East	
				Germany	
8	Bulletin No BS-005/73	All gliders up to fact. No B-	Increase of the distance between flap handle and air	At user's decision	
0	"PIRAT"	550 incl.	brake handle in the cockpit	To be introduced	
9	Bulletin No BE-006/73 "PIRAT"	All gliders up to fact. No B-569 incl.	Periodic inspection of the elevator outer hinges	To be introduced immediately	
10	Bulletin No BR-007/73		Fixing of the elevator outer hinges	At the first main	
10	"PIRAT"	569 incl.	Trixing of the elevator outer filliges	repair or to be	
	I IIVAT	Joy met.		introduced	
				immediately acc. to	
				BE-006/73 "PIRAT"	
11	Bulletin No BK-008/73	All gliders in operation,	Replacement with rivets instead of screws fitting the	To be introduced	
	"PIRAT"	repairs and current production in 1973	front hook	immediately	

Actual status: 1st May 2008

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
12	Bulletin No BE-009/73 "PIRAT"	All gliders up to B-573 incl.	Inspection and strengthening of holes edges in the rear fuselage part	To be introduced immediately	
13	Bulletin No BE-010/73 "PIRAT"	The gliders from W-314 to W-328 from W-389 to W-418 from B-294 to B-596 from S-01.01 to S-04.50	Change of "PIRAT" gliders overhaul life	At user's decision	
14	Bulletin No BK-011/73 "PIRAT"	All gliders to B-573 incl.	Strengthening of fin covering to fuselage connection	Introduce at the nearest repair, but before 500 flying hours	
15	Bulletin No BK-012/74 "PIRAT"	The gliders from W-314 to W-328 from W-389 to W-418 from B-294 to B-596 from S-01.01 to S-03.01	Replacing of the aileron middle hinge fixed to the rear web of the outer wing part	To be introduced immediately	
16	Bulletin No BR-013/74 SZD-30 "PIRAT"/SW	The gliders from S-01.02 to S-01.33 and S-01.35 and S-01.36t	Equivalent of Bulletin BR-001/72 "PIRAT" SZD-30 issued by WSK-Świdnik /item 4 of this list/	ad. 1 at user's decision ad. 2 to be introduced immediately	
17	Bulletin No BR-014/74 SZD-30 "PIRAT"/SW	The gliders from S-01.01 to S-02.08	Equivalent of Bulletin BK-002/72 "PIRAT" issued as above /item 5 of this list/	To be introduced immediately	
18	Bulletin No BR-015/74 SZD-30 "PIRAT"/SW	The gliders from S-01.01 to S-01.29	Equivalent of Bulletin BK-012/74 "PIRAT" issued as above /item 15 of this list/	To be introduced immediately	
19	Bulletin No BR-016/74 "PIRAT"	-	Recovering the previous flight conditions for "PIRAT" gliders	-	Not issued!
20	Bulletin No BR-017/74 SZD-30 "PIRAT"/SW	From S-01.01 to S-03.05	 a/ Performing of drainage holes in root part of wing lower covering b/ Application of the washers under the heads of screws fixing the bracket of the wings for the arm of air-brake control system on the frame No 11 in fuselage 	At the nearest pause during flying	
21	Bulletin No BK-018/75 "PIRAT"/SW	The gliders W-290, from W-314 to W-328, from W-389 to W-418, from B-294 to B-596 and from S-01.01 to S-02.30	Replacement of the rudder /on the "wider" one having the increased taper/	At user's decision /introduction of this Bulletin removes limitations V _{max} from 220 km/h to 250 km/h	

ZAKŁAD SZYBOWCOWY "JEŻÓW" 58-521 Jeżów Sudecki ul. Długa 93

Tel./Fax (33) 829 33 27

Actual status: 1st May 2008

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
22	Bulletin No BK-019/75 "PIRAT"	The gliders W-290, from W-314 to W-328, from W-389 to W-418, from B-294 to B-596 and from S-01.01 to S-02.30	Equivalent of Bulletin BK-018/75 "PIRAT" SW /item 21 of this list/. Elaborated in "PZL-Bielsko"	Introduction of this Bulletin removes limitations V _{max} from 220 km/h to 250 km/h	
23	Bulletin No BI-020/75 "PIRAT"	-	List of bulletins issued up to date /issued in WSK- Świdnik/	For information	
24	Bulletin No BK-021/76 "PIRAT"/SW	The gliders from S-01.01 to S-06.42 incl. and S-06.45 and S-07.01	Fastening of the undercarriage wheel brake clamp on the control stick /elaborated by WSK-Świdnik/	In case of increased play of handle - to be introduced To be introduced immediately	
25	Bulletin No BE-022/80 "PIRAT-C"	The glider X-114 and from P-790 to P-839	Replacement of the normal washer with the special one in aileron-push-rod connection	To be introduced immediately	
26	Bulletin No BK-023/81 "PIRAT"	All glider types SZD-30 "PIRAT" as well as SZD-30B and SZD-30C	Securing of eye push-rod against the possibility of disengage of control circuit caused by shifting the ball bearing out of the end	To be introduced immediately	
27	Bulletin No BI-024/82 "PIRAT"	-	List of bulletins issued up to date for SZD-30, SZD-30B and SZD-30C glider types	For information	
28	Bulletin No BR-025/82 "PIRAT"	All gliders of SZD-30, SZD- 30B and SZD-30C types produced by PDPS-Bielsko, PDPS-Jeżów and WSK- Świdnik	The duraluminium fork-end with the groove being the part of the elevator control system vertical push-rod has to be replaced with the same type one but of steel	To be introduced immediately when this Bulletin is obtained	
29	Bulletin No BR-026/87 "PIRAT"	Gliders of SZD-30C "PIRAT- C" type from P-790 to P-836 incl.	Inspection of aileron deflections to be as required in Technical Service Manual and checking of dimensions of wing aprons in the aileron portion	To be introduced immediately when this Bulletin is obtained	
30	Bulletin No BE-027/87 "PIRAT"	Gliders of SZD-30 "PIRAT" type from W-314 to W-328, from W-389 to W-418 and from B-294 to B-596	Concerns the SZD-30 "PIRAT" gliders having 1800 flying hours completed	To be introduced immediately when the flying-hours limit is reached	
31	Bulletin No BI-028/90 "PIRAT"	All gliders of SZD-30, SZD- 30B and SZD-30C type	Updating of "List of Bulletins issued up to date for "PIRAT" type gliders (updated on 31.07.1990)	For information	
32	Bulletin No BE-029/90 "PIRAT"	All gliders of SZD-30 "Pirat" produced by WSK-Świdnik from S.01 to S.09	Extension of the statements of Bulletin No BE-027/87 "Pirat" for the SZD-30 "Pirat" type gliders produced in 1974/79 by "WSK-Świdnik" factory /life-time of 2600 flying hours/	Acc. to user's decision	

ZAKŁAD SZYBOWCOWY "JEŻÓW" 58-521 Jeżów Sudecki ul. Długa 93

Tel./Fax (33) 829 33 27

Actual status: 1st May 2008

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
33	Bulletin No BE-030/90	All gliders of SZD-30	Extension of the life-time of SZD-30 "Pirat" gliders /as	Acc. to user's decision	
	"PIRAT"	"PIRAT" produced by WSK-	a type/ up to 3200 flying hours		
		Świdnik, "PZL-Bielsko" and			
		"PZL-Wrocław" factories			
34	Bulletin No BK-031/92	All gliders of SZD-30	Additional inspection hole in the fuselage rear floor	Acc. to user's decision	
	"PIRAT"	"PIRAT" type produced by	under the wing	/the change	
		"PZL-Bielsko", "PZL-		recommended by the	
		Wrocław" and "WSK-		producer/	
		Świdnik" factories			
35	Bulletin No BE-032/92	All gliders of SZD-30	Completation of linear dimensions of the deflections of	After this Bulletin is	
	"PIRAT"	"PIRAT" type produced by	"extended" rudder /78-00-00/ in the actual Manuals	received	
		"PZL-Bielsko", "PZL-			
		Wrocław" and "WSK-			
		Świdnik" factories			
36	Bulletin No BS-033/93	Gliders of SZD-30 "PIRAT"	Inspection of glue joints on the rectangular wing portion	Immediately /before	
	"PIRAT"	from W-314 to W-328 incl.	of SZD-30 "Pirat" gliders of "W" series /Fact. Nos	flying season starts/	
		and from W-389 to W-418	beginning with letter W/		
		incl.			
37	Bulletin No BE-034/93	All SZD-30C "PIRAT" gliders,	Extension of life-time of SZD-30C "PIRAT C" gliders	Obligatory when the	
	"PIRAT-C"	/of Fact. Nos initiated with	having completed 1800 flying hours	up-to day allowed	
		letter "P"/		life-time is reached	
38	Bulletin No BA-035/96	All "PIRAT" gliders, which	Permanent location of the inspection hole cap at right	To be introduced	
	"PIRAT"	has the inspection hole cap	side of the seat pan	immediately when	
		dia. 60mm situated at right		this Bulletin is	
		side of the seat pan		obtained	
39	Bulletin No BE-	All produced gliders	Conditions for further operations	To be introduced	
	035/30/2010	SZD-30 Pirat		immediately when	
		SZD-30C Pirat		this Bulletin is	
				obtained	