

LIST OF SERVICE BULLETINS ISSUED FOR PW-5 “SMYK” SAILPLANES.

Item	Bulletin no.	Subject	Effectivity: Sailplanes operated of serial numbers:
1.	1/PW-5/94 mandatory 16.08.94	The max takeoff weight and empty weight changes.	Gliders s/n 17.02.001 and 17.02.002
2.	2/PW-5/94 advisory 08.11.94	Replacement of the measurement units in the FM and MM.	Gliders equipped with the instrument with the imperial units
3.	1/PW-5/95 mandatory 21.06.95	Inspecting the hook mechanism for proper operation.	17.02.001 ÷ 17.02.005, 17.03.001 ÷ 17.03.006, 17.03.009, 17.03.012
4.	2/PW-5/95 reference 14.11.95	Installation of the airbrake lever sealing.	17.02.001 ÷ 17.02.005, 17.03.001 ÷ 17.03.015, (except 17.03.010)
5.	3/PW-5/96 mandatory 10.09.96	Revisions of operations documentation.	Up to S/N 17.05.020 (except 17.03.010, 17.03.021, 17.04.007)
6.	4/PW-5/97 mandatory 20.03.97	New issue of the sailplane Flight Manual, doc. No. PW-5/PWL/III/97	from 17.07.010
7.	5/PW-5/97 reference 24.06.97	Modified position of static pressure transmitters.	up to 17.07.009
8.	6/PW-5/97 mandatory 01.07.97	Check of canopy frame profile shape within the bumper area.	17.02.002 ÷ 17.02.005, 17.03.001 ÷ 17.03.025, (except 17.03.010, 17.03.025), 17.04.001 ÷ 17.04.025, (except 17.04.007), 17.05.001 ÷ 17.05.016, (except 17.05.004, 17.05.009,17.05.014)
9.	6/PW-5/97/1 mandatory 04.11.97	Correction of errors in the text of bulletin No. 6/PW-5/97	as in Bulletin No. 6/PW-5/97.
10.	7/PW-5/97 reference 24.06.97	Installation of new canopy jettisoning system on the PW-5 sailplane.	up to 17.07.013 (except 17.06.018).
11.	8/PW-5/97 mandatory 23.07.97	Replacement of canopy lock handles.	up to 17.08.018 , (except 17.08.011)
12.	9/PW-5/97 advisory 30.12.97	Revisions in the PW-5 sailplane Maintenance Manual doc. No. PW-5/IOT/II/94	from 17.10.001 .
13.	BS-17-99-10 reference 30.03.99	Revisions to operation and maintenance documentation.	from 17.12.018 .
14.	BT-17-99-11 technical 06.12.99	Revision to the descriptive and operational documentation of PW-5 sailplanes operated in Argentina, as per the requirements of RNDA.	Sailplanes operated in Argentina .
15.	BI-17-00-12 advisory 11.02.00	Furnishing the sailplanes with a special ballast.	All sailplanes in operation.
16.	BS-17-00-13 service 07.06.00	Installation of the total pressure system and total energy probe.	17.12.003, 17.12.004, 17.12.005, 17.12.006, 17.12.007, 17.12.008

17.	AD No SP-0028-2001-A and BO-17-01-14 mandatory 02.03.01	Inspection of adhesive-bonded joint for technical condition.	For sailplanes from 17.12..... series.
18.	AD No SP-0129-2001-A and BO-17-01-15 mandatory 15.11.01	Inspection of adhesive-bonded joint for technical condition.	For sailplanes from 17.06.... and 17.07... series.
19.	AD No SP-0003-2002-A and BO-17-02-16 mandatory 14.01.02	Inspection of adhesive-bonded joint for technical condition, and repair procedure.	All sailplanes in operation.
20.	BT-17-02-17 technical 19.06.02	Revision to the Maintenance Manual	Applicable to PW-5 sailplanes operated in Argentina only.
21.	1-2001 technical notice by TOST 01.03.2001	Change of TBO of tow releases and safety releases.	Maximum TBO between 2 general overhauls = 2000 launches, (that means 10.000 releases/actuations)
22.	AD No SP-0086-2003-A, and BO-17-03-18 mandatory 22.12.03	Inspection of push-rod ends	Applicable to sailplanes s/n 17.12.022 to 17.12.024
23.	BS-17-08-19/ZSJ EASA.A.C.08936 mandatory 21.02.2008	Increase of flight altitude limit from 5000m up to 11000m	All serviceable sailplanes
24.	Technical bulletin BT-17-08-20/ZSJ EASA.A.C.08936 not obligatory	Installation of FLUID POWER A14 oxygen equipment	All sailplanes, acc. to User's need.
25	BS-17-19-21/ZSJ service 22.03.2019	Extension of sailplane service life	All sailplanes, at operators discretion