

## LIST OF SERVICE BULLETINS ISSUED FOR PW-6U.

Item	Bulletin no.	Subject	Effectivity: Sailplanes operated of serial numbers:
1.	<b>BS-78-01-01 service</b> 15.05.01	Revisions to Flight and Maintenance Manuals.	Gliders s/n: 78.01.03 through 78.01.07; 78.02.01 through 78.02.04
2.	<b>BS-78-01-03 service</b> 12.12.01	Implementation of revisions to descriptive and maintenance documentation.	78.02.05 sailplane operated in AUSTRIA.
3.	<b>BS-78-02-02 service</b> 15.01.02	Implementation of revisions to descriptive and operational documentation (referring to change of rear canopy emergency jettison system).	Gliders s/n: 78.01.03, 78.01.04, 78.01.05, 78.01.06, 78.01.07, 78.02.01, 78.02.02, 78.02.03, 78.02.04, 78.02.05, 78.02.06, 78.02.07, 78.02.08
4.	<b>BS-78-02-04 service</b> 18.06.03	Installation of automatic elevator connection to control system	<i>All PW-6U sailplanes without automatic elevator connection.</i>
5.	<b>BT-78-02-05 technical</b> 16.12.02	Installation of “SWOL” assy for visualization of rear sailplane canopy opening	Serviceable sailplanes up to s/n 78.03.02.
6	<b>AD No SP-0085-2003-A and BO-78-03-06 mandatory</b> 22.12.03	Inspection of push-rod ends	Sailplanes s/n 78.02.07 to 78.02.10 and 78.03.01 to 78.03.03
8	<b>BS-78-04-07 service</b> 03.12.04	Installation the Roeger hook in the front canopy.	Sailplanes s/n 78.00.00, 78.01.01 – 78.01.07; 78.02.01 – 78.02.09 and 78.03.01 – 78.03.03
9	<b>BO-78-04-08 mandatory</b> 03.12.04	Detailed description of rear canopy assembly and setting adjustment.	All gliders
10	<b>BS-78-04-09 service</b> 09.03.05	Extension of sailplane service life.	All gliders
11	<b>BO-78-10-10</b>	Inspection of the rear attachment fitting of the horizontal stabilizer	Sailplanes s/n 78.03.08-78.03.10, 78.04.01-78.04.09, as well as all other gliders with modification according to bulletin BS-78-02-04 performed
12	<b>BS-78-19-11/ ZSJ service</b> 22.03.2019	Extension of sailplane service life	All gliders, at operators discretion